




Steady State Analysis $h=10,000 \text{ W/m}^2\text{K}$



Steady State Analysis $h=50,000 \text{ W/m}^2\text{K}$



Steady State Analysis $h=1,000 \text{ W/m}^2\text{K}$



Two Dimensional Steady State Conduction

